



**BlueVerse Embedded (WinCE6/WinCE7)
Software Release Notes**
with 06.03.02.00 Update

Ver. 1.0

BlueVerse

The products described in this document are licensed products of the Hyosung Corporation. All unauthorized use or duplication of this information is strictly prohibited.

Windows® is a registered trademark of the Microsoft Corporation.

Table of Contents

1	Introduction.....	2
1.1	Audience.....	2
2	BlueVerse Embedded Software Releases.....	Error! Bookmark not defined.
3	BlueVerse Embedded Release 06.03.02.00 Update.....	3
3.1	Enhancements	3
3.2	Fixes.....	3
3.3	Restrictions.....	3
3.4	Release Date	3

Revision History

Version	Date	Change Summary
1.0	11/6/2023	Created document.

1 Introduction

This is the base set of release notes for Hyosung's BlueVerse Embedded application. These notes provide a high-level overview of the features and functions available in BlueVerse Embedded I and define the hardware and software required by the application.

As patch-level releases are issued for BlueVerse Embedded, addendum documents will be issued that contain, at a minimum, a list of fixes, and may also include a list of enhancements and any known restrictions. These addendums will be attached to this base release notes document.

1.1 Audience

This document is written for ATM network, and retail personnel who are deploying BlueVerse Embedded, as well as Hyosung Professional Services personnel who are supporting those deployments. In addition, anyone wanting to learn about BlueVerse Embedded would benefit from reading selected sections of this document.

2 BlueVerse Embedded Release 06.03.02.00 Update

This section contains information about the 06.03.02.00 software update that has been issued for BlueVerse Embedded.

2.1 Enhancements

The following enhancement is included in this release.

1. [RWC6-568] Remove the requirement that an ATM needs to use TLS.

2.2 Fixes

The following fixes were included in this release.

Hyosung Issue #	Description
RWC6-573	Problem: There is a MAC mismatch that is causing transactions to be reversed. Solution: Updated the application to fix the issue with the MAC mismatch.
RWC6-582	Problem: Font size is not ADA compliant. Solution: Update the application to make the font size ADA compliant.
RWC6-583	Problem: There is an extra character in the messages STD1 Solution: Suppress the extra character in STANDARD1 messages.

2.3 Restrictions

None

2.4 Release Date

11/6/2023